

Inspection Photos

Location Name: TEP ROCKY MOUNTAIN LLC CLOUGH RMV 232-28 Pad

Location ID: 324163



Photo # 6724 From entrance to location



Photo # 6725 Location

Inspection Photos

Location Name: TEP ROCKY MOUNTAIN LLC CLOUGH RMV 232-28 Pad

Location ID: 324163



Photo # 3384 From Inspection 708900170 on 03/27/2023



Photo # 6727 Repaired BMP's

Inspection Photos

Location Name: TEP ROCKY MOUNTAIN LLC CLOUGH RMV 232-28 Pad

Location ID: 324163



Photo # 3387 From Inspection 708900170 on 03/27/2023



Photo # 6728 Repaired BMP's

Inspection Photos

Location Name: TEP ROCKY MOUNTAIN LLC CLOUGH RMV 232-28 Pad

Location ID: 324163



Photo # 3391 From Inspection 708900170 on 03/27/2023



Photo # 6729 Spur road

Inspection Photos

Location Name: TEP ROCKY MOUNTAIN LLC CLOUGH RMV 232-28 Pad

Location ID: 324163



Photo # 3389 From Inspection 708900170 on 03/27/2023



Photo # 6730 Spur road