

Inspection Photos

Location Name: TEP ROCKY MOUNTAIN LLC CLOUGH 113 Pad

Location ID: 311536



Photo # 6870 From entrance to location



Photo # 6871 Location



COLORADO
Oil & Gas Conservation
Commission
Department of Natural Resources

Inspection Photos

Location Name: TEP ROCKY MOUNTAIN LLC CLOUGH 113 Pad

Location ID: 311536



Photo # 6872 Location



COLORADO
Oil & Gas Conservation
Commission
Department of Natural Resources

Inspection Photos

Location Name: TEP ROCKY MOUNTAIN LLC CLOUGH 113 Pad

Location ID: 311536



Photo # 5347 From Inspection 708900287 on 04/13/2023



Photo # 6874 Meter calibration info not conspicuously posted

Inspection Photos

Location Name: TEP ROCKY MOUNTAIN LLC CLOUGH 113 Pad

Location ID: 311536



Photo # 5348 From Inspection 708900287 on 04/13/2023



Photo # 6876 Meter calibration info not conspicuously posted



COLORADO
Oil & Gas Conservation
Commission
Department of Natural Resources

Inspection Photos

Location Name: TEP ROCKY MOUNTAIN LLC CLOUGH 113 Pad

Location ID: 311536



Photo # 5349 From Inspection 708900287 on 04/13/2023



Photo # 6877 Meter calibration info not conspicuously posted



COLORADO
Oil & Gas Conservation
Commission
Department of Natural Resources

Inspection Photos

Location Name: TEP ROCKY MOUNTAIN LLC CLOUGH 113 Pad

Location ID: 311536



Photo # 5351 From Inspection 708900287 on 04/13/2023



Photo # 6879 Check dams need maintenance



COLORADO
Oil & Gas Conservation
Commission
Department of Natural Resources

Inspection Photos

Location Name: TEP ROCKY MOUNTAIN LLC CLOUGH 113 Pad

Location ID: 311536



Photo # 6880 Check dams need maintenance



Photo # 6884 Check dams need maintenance