

Inspection Photos

May 2, 2023

Operator: Caerus Piceance LLC - #10456

Location ID: 335359

Location Name: KELL-66S93W/35NENW

Inspection Document #: 702801492

Garfield County, CO

NENW Section 35 T6S R93W

Anna O'Malley
Reclamation Specialist, COGCC



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

Inspection Photos
Location Name: KELL-66S93W/35NENW
Location ID: 335359



Photo 1. Photos show production areas.

Inspection Photos
Location Name: KELL-66S93W/35NENW
Location ID: 335359



Photo 2. Photos show unused flowline risers from previous inspection (left) have been removed (right).



Inspection Photos

Location Name: KELL-66S93W/35NENW

Location ID: 335359



Photo 3. Photos show lack of stabilization of the pad surface to the south.



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

Inspection Number: 702801492

Inspection Photos
Location Name: KELL-66S93W/35NENW
Location ID: 335359



Photo 4. Photos show slopes to the north of the location lack stabilization



Inspection Photos
Location Name: KELL-66S93W/35NENW
Location ID: 335359



Photo 5. Photos show slopes to the northwest of the location lack stabilization. Photo also shows dead livestock (left).



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

Inspection Number: 702801492

Inspection Photos
Location Name: KELL-66S93W/35NENW
Location ID: 335359



Photo 6. Photos show slopes to the northeast of the location lack stabilization.

Inspection Photos
Location Name: KELL-66S93W/35NENW
Location ID: 335359



Photo 7. Photos show the interim area/slopes to the southwest. Slopes are sparsely vegetated and stable at this time.



Photo . Photo show slopes becoming progressively less vegetated and more unstable to the north.



Inspection Photos

Location Name: KELL-66S93W/35NENW

Location ID: 335359



Photo 8. Photos taken from the south show an overview of the interim area. Grasses appear sparsely established. Photo also shows dead livestock (left).



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

Inspection Number: 702801492

Inspection Photos

Location Name: KELL-66S93W/35NENW

Location ID: 335359



Photo 9. Photo shows noxious thistle rosettes near the wellheads.



COLORADO

Oil & Gas Conservation
Commission

Department of Natural Resources

Inspection Number: 702801492