

Inspection Photos

Location Name: TEP ROCKY MOUNTAIN LLC CLOUGH 2A pad

Location ID: 335244



Photo # 6889 From entrance to location



Photo # 6890 Location

Inspection Photos

Location Name: TEP ROCKY MOUNTAIN LLC CLOUGH 2A pad

Location ID: 335244



Photo # 6891 Location



Photo # 6892 Location

Inspection Photos

Location Name: TEP ROCKY MOUNTAIN LLC CLOUGH 2A pad

Location ID: 335244



May 4, 2023 at 9:23:31 AM
CO



May 4, 2023 at 9:23:57 AM
CO

Photo # 6900 Location

Photo # 6901 Location

Inspection Photos

Location Name: TEP ROCKY MOUNTAIN LLC CLOUGH 2A pad

Location ID: 335244



**Photo # 4480 From Inspection 708900246 on 04/06/2023
Meter calibration info not conspicuously posted**



Photo # 6904 Meter calibration info not conspicuously posted