

Inspection Photos

Location Name: TEP ROCKY MOUNTAIN LLC CLOUGH RMV 94-21 Pad

Location ID: 335210



Photo # 6908 From entrance to location



Photo # 6909 Location

Inspection Photos

Location Name: TEP ROCKY MOUNTAIN LLC CLOUGH RMV 94-21 Pad

Location ID: 335210



Photo # 6910 Location



Photo # 6911 Location

Inspection Photos

Location Name: TEP ROCKY MOUNTAIN LLC CLOUGH RMV 94-21 Pad

Location ID: 335210



**Photo # 4545 From Inspection 708900249 on 04/07/2023
Meter calibration info not conspicuously posted**



Photo # 6913 Meter calibration info not conspicuously posted

Inspection Photos

Location Name: TEP ROCKY MOUNTAIN LLC CLOUGH RMV 94-21 Pad

Location ID: 335210



**Photo # 4546 From Inspection 708900249 on 04/07/2023
Meter calibration info not conspicuously posted**



Photo # 6914 Meter calibration info not conspicuously posted

Inspection Photos

Location Name: TEP ROCKY MOUNTAIN LLC CLOUGH RMV 94-21 Pad

Location ID: 335210



Photo # 6921 Open cellar/wildlife hazard (Cellar is just off lease road approximately 25-50 yards past CLOUGH 2A pad)



Photo # 6922 Open cellar/wildlife hazard (Cellars are just off lease road approximately 25-50 yards past CLOUGH 2A pad)