

CAERUS PICEANCE LLC, GASAWAY-66S99W/20NESE

Location # 324233



Location Entrance – Photo #02783



Wellhead – Photo #02785

CAERUS PICEANCE LLC, GASAWAY-66S99W/20NESE

Location # 324233



Separator/Gas Meter/Lack of Stabilization – Photo #02789



Tank Battery – Photo #02792



COLORADO
Oil & Gas Conservation
Commission
Department of Natural Resources

CAERUS PICEANCE LLC, GASAWAY-66S99W/20NESE

Location # 324233



Unused Equipment Stored on Location – Photo #02791



Unused Equipment Stored on Location – Photo #02796

CAERUS PICEANCE LLC, GASAWAY-66S99W/20NESE

Location # 324233



Access Road Lacks Stabilization – Photo #02797



Rill Erosion Across Access Road/Insufficient Vehicle Tracking BMPs – Photo #02798