

Inspection Photos
Well Name: Ocoma 31-19
API #05-123-14917



Photo #1 Well / No sign

Photo #2 No sign

Inspection Photos
Well Name: Ocoma 31-19
API #05-123-14917



Photo #3 Unused Equipment “solar panel”