

## Inspection Photos

Location Name: CAERUS PICEANCE LLC COUEY I8E Pad

Location ID: 334907



Photo # 7055 From entrance to location



Photo # 7056 From entrance to location





**Inspection Photos**  
**Location Name: CAERUS PICEANCE LLC COUEY I8E Pad**  
**Location ID: 334907**



**Photo # 7058 Location**



**Photo # 7060 Location**

## Inspection Photos

Location Name: CAERUS PICEANCE LLC COUEY I8E Pad

Location ID: 334907



**Photo # 7061 Location**



**Photo # 7092 Chemical BMP 2/3 to 3/4 full of fluid/failure to maintain chemical BMP**



**Inspection Photos**  
**Location Name: CAERUS PICEANCE LLC COUEY I8E Pad**  
**Location ID: 334907**



**Photo # 7063 Open ended piping/wildlife hazard**



**Photo # 7104 Unmarked deadman**