

## Inspection Photos

Location Name: TEP ROCKY MOUNTAIN LLC RMV 64-20 Pad

Location ID: 335283



May 5, 2023 at 9:40:07 AM  
CO



May 5, 2023 at 9:40:12 AM  
CO

Photo # 7012 From entrance to location

Photo # 7013 From entrance to location



## Inspection Photos

Location Name: TEP ROCKY MOUNTAIN LLC RMV 64-20 Pad

Location ID: 335283




Photo # 7014 Location



Photo # 7015 Location



**COLORADO**  
Oil & Gas Conservation  
Commission  
Department of Natural Resources

## Inspection Photos

Location Name: TEP ROCKY MOUNTAIN LLC RMV 64-20 Pad

Location ID: 335283



Photo # 7016 Location



Photo # 7017 Open ended load line



COLORADO  
Oil & Gas Conservation  
Commission  
Department of Natural Resources



## Inspection Photos

Location Name: TEP ROCKY MOUNTAIN LLC RMV 64-20 Pad

Location ID: 335283



**Photo # 7019 Meter calibration info not conspicuously posted**



**Photo # 7020 Meter calibration info not conspicuously posted**