

Inspection Photos

Location Name: TEP ROCKY MOUNTAIN LLC RMV 5-21 Pad

Location ID: 323888



Photo # 6925 From entrance to location



Photo # 6926 Location

Inspection Photos
Location Name: TEP ROCKY MOUNTAIN LLC RMV 5-21 Pad
Location ID: 323888



Photo # 6927 Location



Photo # 6933 Same unmarked deadman from a different vantage point

Inspection Photos

Location Name: TEP ROCKY MOUNTAIN LLC RMV 5-21 Pad

Location ID: 323888



Photo # 5333 From Inspection 708900277 conducted on 04/13/2023 Unmarked deadman

Photo # 6930 Unmarked deadman

Inspection Photos

Location Name: TEP ROCKY MOUNTAIN LLC RMV 5-21 Pad

Location ID: 323888



Photo # 5330 From Inspection 708900277 conducted on 04/13/2023 Meter calibration info not conspicuously posted



Photo # 6929 Meter calibration info not conspicuously posted