

Inspection Photos

Location Name: TEP ROCKY MOUNTAIN LLC RMV 220-21 Pad

Location ID: 335334



Photo # 6936 From entrance to location

Photo # 6937 From entrance to location

Inspection Photos

Location Name: TEP ROCKY MOUNTAIN LLC RMV 220-21 Pad

Location ID: 335334



Photo # 6940 Location



Photo # 6941 Location

Inspection Photos

Location Name: TEP ROCKY MOUNTAIN LLC RMV 220-21 Pad

Location ID: 335334



Photo # 6942 Location



Photo # 6943 Debris

Inspection Photos

Location Name: TEP ROCKY MOUNTAIN LLC RMV 220-21 Pad

Location ID: 335334



Photo # 5311 From Inspection 708900275 conducted on 04/13/2023 Meter calibration info not conspicuously posted

Photo # 6945 Meter calibration info not conspicuously posted