

## Inspection Photos

Location Name: TEP ROCKY MOUNTAIN LLC CLOUGH RMV 205-20 Pad

Location ID: 324057



Photo # 6974 From entrance to location



Photo # 6975 From entrance to location

## Inspection Photos

Location Name: TEP ROCKY MOUNTAIN LLC CLOUGH RMV 205-20 Pad

Location ID: 324057



Photo # 6976 Location



Photo # 6977 Location

## Inspection Photos

Location Name: TEP ROCKY MOUNTAIN LLC CLOUGH RMV 205-20 Pad

Location ID: 324057



Photo # 6978 Location

## Inspection Photos

Location Name: TEP ROCKY MOUNTAIN LLC CLOUGH RMV 205-20 Pad

Location ID: 324057



**Photo # 4138 From Inspection 708900215 conducted on 04/04/2023 Meter calibration info not conspicuously posted**



**Photo # 6982 Meter calibration info not conspicuously posted**