

LARAMIE ENERGY LLC, CC/0797-05-36 Pad

Location # 335187



Location – Photo #02906



Wellheads – Photo #02909

LARAMIE ENERGY LLC, CC/0797-05-36 Pad

Location # 335187



Separators – Photo #02914



Tank Battery – Photo #02915



LARAMIE ENERGY LLC, CC/0797-05-36 Pad

Location # 335187



**Cut Slope Eroding into Production Equipment –
Photo #02917**



**Cut Slope Eroding into Production Equipment –
Photo #02918**

LARAMIE ENERGY LLC, CC/0797-05-36 Pad

Location # 335187



Location Lacks Stabilization – Photo #02919



**Insufficient Tracking BMPs at Location Entrance/Exit
– Photo #02959**