

LARAMIE ENERGY LLC, CC/0797-06-07 Pad

Location # 335480



Location – Photo #02941

Wellheads – Photo #02950

LARAMIE ENERGY LLC, CC/0797-06-07 Pad

Location # 335480



Separators – Photo #02944



Tank Battery – Photo #02947

LARAMIE ENERGY LLC, CC/0797-06-07 Pad

Location # 335480



Cut Slope Eroding onto Location – Photo #02945



Location Lacks Stabilization – Photo #02949

LARAMIE ENERGY LLC, CC/0797-06-07 Pad

Location # 335480



**Insufficient Vehicle Tracking BMPs at Location
Entrance/Exit – Photo #02953**