

## Storm water Management and Erosion control

Location Name: CLOUGH 134 Pad

Location #: 322440



North West corner of location.



North East corner of location.



South West corner of location.



South East corner of location.



**COLORADO**  
Oil & Gas Conservation  
Commission  
Department of Natural Resources



## Storm water Management and Erosion control

Location Name: CLOUGH 134 Pad

Location #: 322440



Photo # 5072 From Inspection 708900279 conducted on 04/12/2023 Lack of stabilization/compaction



Photo # 7145 Lack of stabilization/compaction



## Storm water Management and Erosion control

Location Name: CLOUGH 134 Pad

Location #: 322440



Photo # 5073 From Inspection 708900279 conducted on  
04/12/2023 Lack of stabilization/compaction



Photo # 7148 Lack of stabilization/compaction



## Storm water Management and Erosion control

Location Name: CLOUGH 134 Pad

Location #: 322440



Photo # 5074 From Inspection 708900279 conducted on 04/12/2023 Lack of stabilization/compaction



Photo # 7152 Lack of stabilization/compaction

## Storm water Management and Erosion control

Location Name: CLOUGH 134 Pad

Location #: 322440



Photo # 5075 From Inspection 708900279 conducted on 04/12/2023 Lack of stabilization/compaction



Photo # 7155 Lack of stabilization/compaction



**COLORADO**  
Oil & Gas Conservation  
Commission  
Department of Natural Resources



## Storm water Management and Erosion control

Location Name: CLOUGH 134 Pad

Location #: 322440



Photo # 7156 Lack of stabilization/compaction



Photo # 7157 Lack of stabilization/compaction



## Storm water Management and Erosion control

Location Name: CLOUGH 134 Pad

Location #: 322440



Photo # 7158 Lack of stabilization/compaction



Photo # 7159 Lack of stabilization/compaction



## Storm water Management and Erosion control

Location Name: CLOUGH 134 Pad

Location #: 322440



Photo # 5076 From Inspection 708900279 conducted on 04/12/2023 Erosion & transport of sediment onto location



Photo # 7166 Erosion & transport of sediment onto location



**COLORADO**  
Oil & Gas Conservation  
Commission  
Department of Natural Resources



## Storm water Management and Erosion control

Location Name: CLOUGH 134 Pad

Location #: 322440



Photo # 5078 From Inspection 708900279 conducted on 04/12/2023 Erosion & transport of sediment onto location



Photo # 7167 Erosion & transport of sediment onto location



## Storm water Management and Erosion control

Location Name: CLOUGH 134 Pad

Location #: 322440



Photo # 5079 From Inspection 708900279 conducted on 04/12/2023 Erosion & transport of sediment onto location



Photo # 7175 Erosion & transport of sediment onto location