

Inspection Photos

Location Name: TEP ROCKY MOUNTAIN LLC CLOUGH 134 Pad

Location ID: 322440



Photo # 7135 From entrance to location



Photo # 7136 From entrance to location

Inspection Photos

Location Name: TEP ROCKY MOUNTAIN LLC CLOUGH 134 Pad

Location ID: 322440



Photo # 7137 Location



Photo # 7138 Location



COLORADO
Oil & Gas Conservation
Commission
Department of Natural Resources

Inspection Photos

Location Name: TEP ROCKY MOUNTAIN LLC CLOUGH 134 Pad

Location ID: 322440



Photo # 7140 Location



Photo # 7141 Location



Inspection Photos

Location Name: TEP ROCKY MOUNTAIN LLC CLOUGH 134 Pad

Location ID: 322440



Photo # 5094 From Inspection 708900279 conducted on 04/12/2023 Meter calibration info not conspicuously posted



Photo # 7143 Meter calibration info not conspicuously posted