

Inspection Photos

Location Name: TEP ROCKY MOUNTAIN LLC RMV 204-20 Pad

Location ID: 335381



Photo # 7218 From entrance to location



Photo # 7219 From entrance to location

Inspection Photos

Location Name: TEP ROCKY MOUNTAIN LLC RMV 204-20 Pad

Location ID: 335381



Photo # 7220 Location



Photo # 7221 Location

Inspection Photos

Location Name: TEP ROCKY MOUNTAIN LLC RMV 204-20 Pad

Location ID: 335381



Photo # 7222 Location



Photo # 7224 Meter calibration info not conspicuously posted

Inspection Photos

Location Name: TEP ROCKY MOUNTAIN LLC RMV 204-20 Pad

Location ID: 335381



Photo # 7225 Meter calibration info not conspicuously posted