

## Inspection Photos

Location Name: TEP ROCKY MOUNTAIN LLC CLOUGH RWF 413-20 Pad

Location ID: 335217



Photo # 7186 From entrance to location



Photo # 7187 From entrance to location

## Inspection Photos

Location Name: TEP ROCKY MOUNTAIN LLC CLOUGH RWF 413-20 Pad

Location ID: 335217



Photo # 7188 Location



Photo # 7189 Location

## Inspection Photos

Location Name: TEP ROCKY MOUNTAIN LLC CLOUGH RWF 413-20 Pad

Location ID: 335217



Photo # 7195 Location



Photo # 7196 Location

## Inspection Photos

Location Name: TEP ROCKY MOUNTAIN LLC CLOUGH RWF 413-20 Pad

Location ID: 335217



Photo # 4147 From Inspection 708900228 conducted on 04/04/2023 Meter calibration info not conspicuously posted



Photo # 7190 Meter calibration info not conspicuously posted

## Inspection Photos

Location Name: TEP ROCKY MOUNTAIN LLC CLOUGH RWF 413-20 Pad

Location ID: 335217



Photo # 4148 From Inspection 708900228 conducted on 04/04/2023 Meter calibration info not conspicuously posted

Photo # 7194 Meter calibration info not conspicuously posted