

Inspection Photos
Location Name: A.C.N.O. #2
Location ID: 311322



Photo 1 WH sign faded hard to read needs replaced.



Photo 2 Stained soil around the WH.



Inspection Photos
Location Name: A.C.N.O. #2
Location ID: 311322



Photo 3 Stained soil around the WH.



Photo 4 Leaking WH.

Inspection Photos
Location Name: A.C.N.O. #2
Location ID: 311322



Photo 5 PW vessel.



Photo 6 PW vessel (Tin Horn) not in use.

Inspection Photos
Location Name: A.C.N.O. #2
Location ID: 311322



Photo 7 Tin Horn not in use.



Photo 8 Gas Meter Run.

Inspection Photos
Location Name: A.C.N.O. #2
Location ID: 311322



Photo 9 Gas Meter Run.



Photo 10 Door/frame off of the Gas Meter Run Housing (trash).

Inspection Photos
Location Name: A.C.N.O. #2
Location ID: 311322



Photo 11 TB sign.



Photo 12 TB



Inspection Photos
Location Name: A.C.N.O. #2
Location ID: 311322



Photo 13 Stained soil around the PW Tank inside berm.



Photo 14 Stained soil in tank battery berm.

Inspection Photos
Location Name: A.C.N.O. #2
Location ID: 311322



Photo 15 Stained soil between the crude tank & PW Tank.



Photo 16 Crude tank leak.