

LARAMIE ENERGY LLC, CC/0697-20-28 Pad

Location # 335150



NW Corner of Location – Photo #02979



SE Corner of Location – Photo #02981

LARAMIE ENERGY LLC, CC/0697-20-28 Pad

Location # 335150



SW Corner of Location – Photo #02985



Wellheads – Photo #02982

LARAMIE ENERGY LLC, CC/0697-20-28 Pad

Location # 335150



Separators – Photo #02984



Tank Battery – Photo #02986



LARAMIE ENERGY LLC, CC/0697-20-28 Pad

Location # 335150



Cut Slope Eroding onto Location – Photo #02987



Cut Slope Eroding onto Location – Photo #02988

LARAMIE ENERGY LLC, CC/0697-20-28 Pad

Location # 335150



Lack of Stabilization on Access Road – Photo #02993



Insufficient Vehicle Tracking BMPs at Location Entrance/Exit – Photo #02994