

LARAMIE ENERGY LLC, CC/0617-24 Pad

Location # 335404



NW Corner of Location – Photo #02996



SW Corner of Location – Photo #

LARAMIE ENERGY LLC, CC/0617-24 Pad

Location # 335404



SE Corner of Location – Photo #03003



Separators – Photo #02999

LARAMIE ENERGY LLC, CC/0617-24 Pad

Location # 335404



Tank Battery – Photo #03001



Location Lacks Stabilization – Photo #03004



LARAMIE ENERGY LLC, CC/0617-24 Pad

Location # 335404



**Insufficient Vehicle Tracking BMPs at Location
Entrance/Exit – Photo #03005**



**Insufficient Vehicle Tracking BMPs at Location
Entrance/Exit – Photo #03006**