

LARAMIE ENERGY LLC, CC/0697-17-50 Pad

Location # 335903



NE Corner of Location – Photo #03008



SE Corner of Location – Photo #03009

LARAMIE ENERGY LLC, CC/0697-17-50 Pad

Location # 335903



Wellheads – Photo #03019



Separators – Photo #03010




COLORADO
Oil & Gas Conservation
Commission
Department of Natural Resources

LARAMIE ENERGY LLC, CC/0697-17-50 Pad

Location # 335903



Tank Battery – Photo #03011



Cut Slope Eroding onto Location– Photo #03017

LARAMIE ENERGY LLC, CC/0697-17-50 Pad

Location # 335903



Cut Slope Eroding onto Location – Photo #03022



Insufficient Vehicle Tracking BMPs at Location Entrance/Exit – Photo #03023