

# Inspection Photos

API: 071-06204

Operator: EVERGREEN NATURAL RESOURCES

Inspection Date: 5/8/2023



**COLORADO**  
Oil & Gas Conservation  
Commission

Department of Natural Resources

API: 071-06204 | Date: 5/8/2023

## Inspection Photos



**Photo 1.** There is erosion along the access road at this drainage crossing  
Lat/Long:37.05023,-104.66580. This embankment needs to be stabilized.



**COLORADO**  
Oil & Gas Conservation  
Commission

Department of Natural Resources

API: 071-06204 | Date: 5/8/2023

## Inspection Photos



**Photo 2.** Facing toward the wellsite.



**COLORADO**  
Oil & Gas Conservation  
Commission

Department of Natural Resources

API: 071-06204 | Date: 5/8/2023