

# Inspection Photos

API: 071-07607

Operator: EVERGREEN NATURAL RESOURCES

Inspection Date: 5/8/2023



**COLORADO**

**Oil & Gas Conservation  
Commission**

Department of Natural Resources

API: 071-07607 | Date: 5/8/2023

## Inspection Photos



**Photo 1.** Facing southeast toward the access road stream crossing.



**COLORADO**  
Oil & Gas Conservation  
Commission

Department of Natural Resources

API: 071-07607 | Date: 5/8/2023



## Inspection Photos



**Photo 2.** The old unused culverts need to be removed.



**COLORADO**  
Oil & Gas Conservation  
Commission

Department of Natural Resources

API: 071-07607 | Date: 5/8/2023



## Inspection Photos



**Photo 3.** Facing north toward the wellsite.



**COLORADO**  
Oil & Gas Conservation  
Commission

Department of Natural Resources

API: 071-07607 | Date: 5/8/2023



## Inspection Photos



**Photo 4.** Facing northeast toward the fill slope which is stabilized with vegetation.



**COLORADO**  
Oil & Gas Conservation  
Commission

Department of Natural Resources

API: 071-07607 | Date: 5/8/2023



## Inspection Photos



**Photo 5.** Well sign is posted at meter shed.



**COLORADO**  
Oil & Gas Conservation  
Commission

Department of Natural Resources

API: 071-07607 | Date: 5/8/2023