

Inspection Photos

API: 071-06790

Operator: EVERGREEN NATURAL RESOURCES

Inspection Date: 5/8/2023



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

API: 071-06790 | Date: 5/8/2023

Inspection Photos



Photo 1. Facing south along the road at the stream crossing. The culverts have been repaired and bank was regraded. Disturbed areas were seeded and hydromulched.



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

API: 071-06790 | Date: 5/8/2023

Inspection Photos



Photo 2. Facing back northwest toward the stream crossing repair. Disturbed areas were seeded and hydromulched.



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

API: 071-06790 | Date: 5/8/2023

Inspection Photos



Photo 3. Facing southeast toward the wellsite. A diversion berm was installed along the road to the culvert.



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

API: 071-06790 | Date: 5/8/2023