

Inspection Photos

API: 071-07829

Operator: EVERGREEN NATURAL RESOURCES

Inspection Date: 5/8/2023



COLORADO

**Oil & Gas Conservation
Commission**

Department of Natural Resources

API: 071-07829 | Date: 5/8/2023

Inspection Photos



Photo 1. Facing northeast along the road. Culvert outlet protection was installed a disturbed areas were seeded and hydromulched.



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

API: 071-07829 | Date: `5/8/2023

Inspection Photos



Photo 2. Facing northeast along the access road. Rock check dams were installed along the road and disturbed areas were seeded and hydromulched.



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

API: 071-07829 | Date: `5/8/2023

Inspection Photos



Photo 3. Facing north along the access road. Rock check dams were installed along the road and disturbed areas were seeded and hydromulched.



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

API: 071-07829 | Date: `5/8/2023

Inspection Photos



Photo 4. Facing west toward the wellsite.



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

API: 071-07829 | Date: `5/8/2023