

Inspection Photos
Location Name: Anne State 6
Location ID: 326750



Photo 1 – Tank Battery Sign



Photo 2 – Tank Battery

Inspection Photos
Location Name: Anne State 6
Location ID: 326750




Photo 3 – Active Flow Rate on Sales Meter.




Photo 4 – Sales Meter

Inspection Photos
Location Name: Anne State 6
Location ID: 326750



Photo 5 – Sales Meter Valve Open



Photo 6 – Separator

Inspection Photos
Location Name: Anne State 6
Location ID: 326750



Photo 7 – Wellhead