

**Inspection Photos**  
**Location Name: Lost Creek State 1**  
**Location ID: 323364**



COGCC  
40.27114, -104.27437, 4482.9ft  
05/08/2023 12:27:00

**Photo 1 – Gas Engine**



COGCC  
40.27121, -104.27435, 4491.8ft  
05/08/2023 12:27:08


**Photo 2 – Well Sign**



**Inspection Photos**  
**Location Name: Lost Creek State 1**  
**Location ID: 323364**



**Photo 3 – Wellhead**



**Photo 4 – Unmarked Risers**



**Inspection Photos**  
**Location Name: Lost Creek State 1**  
**Location ID: 323364**



**Photo 5 – Stained Soil at Exhaust**




**Photo 6 – Tank Battery – Water Content Label**



**Inspection Photos**  
**Location Name: Lost Creek State 1**  
**Location ID: 323364**



**Photo 7 – Back Drain Valve on Produced Water Tank**



**Photo 8 – Unmarked Risers**



**Inspection Photos**  
**Location Name: Lost Creek State 1**  
**Location ID: 323364**




**Photo 9 – Unmarked Risers in Tank Berm**




**Photo 10 – Unmarked Risers**



**Inspection Photos**  
**Location Name: Lost Creek State 1**  
**Location ID: 323364**




**Photo 11 – Unused Pipes and Valves**




**Photo 12 – Unmarked Risers**



**Inspection Photos**  
**Location Name: Lost Creek State 1**  
**Location ID: 323364**



**Photo 13 – Unmarked Risers and Unused Valve**



**Photo 14 – Unmarked Riser**

**Inspection Photos**  
**Location Name: Lost Creek State 1**  
**Location ID: 323364**



**Photo 15 – Heater Treater**




**Photo 16 – Unmarked Risers**



**Inspection Photos**  
**Location Name: Lost Creek State 1**  
**Location ID: 323364**




**Photo 17 – Gas Meters**



**Photo 18 – Valve Shut**



**Inspection Photos**  
**Location Name: Lost Creek State 1**  
**Location ID: 323364**



**Photo 19 – Gas Sale Valve Tagged Out**



**Photo 20 – Tank Labels**