



00213158

LEASE INSPECTION FORM

Date 7/24/85
Operator TREND EXP. Field BUCK PEAK
Lease Name & No. STATE 2-16 County MOFFAT
Tank Battery No. N/A Location 16-6N-90W
Legal Description
Type of Inspection well site
Water Inflow _____ (Bbls. Per Day)

RESULTS OF INSPECTION

(Est. Pit Dimensions, CVD, Lined, Oil on Surface, etc.)
Type of Tank

SKIM TANK wellhead w/ RUSTED POLISHED ROD
NO PUMPER

Pit No. 1 NO TANKS
1 PIT 8'X20'X8' NEXT TO wellhead

Pit No. 2 _____

Pit No. 3 _____

ADDITIONAL PITS _____

CONDITION OF LEASE (Describe - Oil CVD. or Sat. Gr., Any Leaking, Safety Conditions, Etc.)

VISITED LAST FALL, RECALL IT WAS A HARPER RIG DRILLING AWAY

RECOMMENDED ACTION (If Required) CHECK & SEE IF FORMS ARE IN - BILL

SPECIAL IF NOT

INSPECTOR SSK