

Inspection Photos

Location Name: TEP ROCKY MOUNTAIN LLC RMV 138-21 Pad

Location ID: 324136



Photo # 7252 From entrance to location



Photo # 7253 Location



Inspection Photos

Location Name: TEP ROCKY MOUNTAIN LLC RMV 138-21 Pad

Location ID: 324136



Photo # 7254 Location



Photo # 7255 Location



Inspection Photos

Location Name: TEP ROCKY MOUNTAIN LLC RMV 138-21 Pad

Location ID: 324136



Photo # 5126 From Inspection 708900271 conducted on 04/12/2023 Meter calibration info not conspicuously posted




Photo # 7256 Meter calibration info not conspicuously posted