

Inspection Photos  
Location Name: Strong 4-22  
Location ID: 332567



Photo 1: Wellhead Sign



Photo 2: Wellhead

Inspection Photos  
Location Name: Strong 4-22  
Location ID: 332567



Photo 3: Appears to has sold product



Photo 4: Appears to have sold product



**Inspection Photos**  
**Location Name: Strong 4-22**  
**Location ID: 332567**



**Photo 5: Pressure present on gauges**



**Photo 6: Pressure present on gauges**

**Inspection Photos**  
**Location Name: Strong 4-22**  
**Location ID: 332567**



**Photo 7: Valve appears to be open**



**Photo 8: Valve appears to be open**



**Inspection Photos**  
**Location Name: Strong 4-22**  
**Location ID: 332567**



**Photo 9: Pressure present on gauges**