

Inspection Photos  
Location Name: Amen #1  
Location ID: 319144



Photo 1: Tank Battery Sign



Photo 2: Appears to have sold product

Inspection Photos  
Location Name: Amen #1  
Location ID: 319144



Photo 3: Appears to have sold product



Photo 4: Valves appear to be open, pressure is present on gauge

**Inspection Photos**  
**Location Name: Amen #1**  
**Location ID: 319144**



**Photo 5: Valves appear to be open**



**Photo 6: Valve appears to be open**