


**Inspection Photos**  
**Location Name: Parmlee #3**  
**Location ID: 470289**



**Photo 1 – Gas Meter**



**Photo 2 – LOTO by Gas Operator**

**Inspection Photos**  
**Location Name: Parmlee #3**  
**Location ID: 470289**



**Photo 3 – Tank Battey**



**Photo 4 – Tank Battery Signs**



**Inspection Photos**  
**Location Name: Parmlee #3**  
**Location ID: 470289**



**Photo 5 – Unmarked Riser**




**Photo 6 – Loadline Lid open**

**Inspection Photos**  
**Location Name: Parmlee #3**  
**Location ID: 470289**



**Photo 7 – Heater Treater**



**Photo 8 – NFPA Label**