

Inspection Photos
Location Name: Seyfried #2
Location ID: 470277



Photo 1 – Capacity Label



Photo 2 – Tank Battery

Inspection Photos
Location Name: Seyfried #2
Location ID: 470277



Photo 3 – Separator



Photo 4 – Unmarked Risers

Inspection Photos
Location Name: Seyfried #2
Location ID: 470277



Photo 5 – Wellhead disconnected from Separator



Photo 6 – Sales Line open