

**Inspection Photos**  
**Location Name: State 2-12 Tank Battery**  
**Location ID: 406271**



**Photo 1 – Separator and Tank**



**Photo 2 – Separator and Tank**

**Inspection Photos**  
**Location Name: State 2-12 Tank Battery**  
**Location ID: 406271**



**Photo 3 – Separator Vent Pipe**



**Photo 4 – Overview looking to the North West**



**Inspection Photos**  
**Location Name: State 2-12 Tank Battery**  
**Location ID: 406271**



**Photo 5 – Unused Pipe**



**Photo 6 – Sales Line Disconnected**



**Inspection Photos**  
**Location Name: State 2-12 Tank Battery**  
**Location ID: 406271**



**Photo 7 – Sales Line**



**Photo 8 – Unmarked Riser**



**Inspection Photos**  
**Location Name: State 2-12 Tank Battery**  
**Location ID: 406271**



**Photo 9 – Sign at Entrance**



**Photo 10 – Sign at Entrance**