

**KT Resources LLC
Ant Hill Unit 16-22
Location #316298**



Access road to location



Entrance to location

KT Resources LLC
Ant Hill Unit 16-22
Location #316298



Signs at tank battery



Gas meter calibration not visibly displayed

**KT Resources LLC
Ant Hill Unit 16-22
Location #316298**



Bare ground slopes away from location



Erosion and sediment migration on location

**KT Resources LLC
Ant Hill Unit 16-22
Location #316298**



Vehicle rutting outside gravel area



Erosion and sediment migration sloping off location

**KT Resources LLC
Ant Hill Unit 16-22
Location #316298**



Bare ground sloping off location



Erosion and sediment migration sloping off location

**KT Resources LLC
Ant Hill Unit 16-22
Location #316298**



Location view from Southeast corner



Location view from Southwest corner

**KT Resources LLC
Ant Hill Unit 16-22
Location #316298**



Location view from Northwest corner



Location view from Northeast corner