



RECEIVED
FEB 19 1976
COLO. OIL & GAS CONS. COMM.

JIM SNYDER DRILLING COMPANY
1507 Denver Club Building
Denver, Colorado 80202

PLUGGING REPORT

Well Name Kodak # 2
Location C-SE 1/4 Sec 34-T6N
R67W 6 PM
Operator Colton + Colton

This well was filled with Wt. 10.5 mud.

15 sacks were put at the bottom of surface pipe and 10 sacks at the top of the surface pipe.

Bottom hole plugs (if any) NONE

To my knowledge, no junk was left in the hole.

Signed: A. Bedwin
Toolpusher

JIM SNYDER DRILLING COMPANY

Date 1/18/76
~~1-18-75~~

75-1148