

State of Colorado  
Oil and Gas Conservation Commission

1120 Lincoln Street, Suite 801, Denver, Colorado 80203  
Phone: (303) 894-2100 Fax: (303) 894-2109



Document Number:  
403390612

Date Received:  
05/01/2023

**FIR RESOLUTION FORM**

Overall Status: CAC

CA Summary:

1 of 1 CAs from the FIR responded to on this Form

1 CA Completed  
0 Factual Review Request

**OPERATOR INFORMATION**

OGCC Operator Number: 10409  
Name of Operator: PEAKVIEW OPERATING COMPANY LLC  
Address: 2427 WEST KETTLE CIRCLE  
City: LITTLETON State: CO Zip: 80120

Contact Name and Telephone:  
Name: \_\_\_\_\_  
Phone: ( ) \_\_\_\_\_ Fax: ( ) \_\_\_\_\_  
Email: \_\_\_\_\_

Additional Operator Contact:

Contact Name	Phone	Email
<u>Wise, Wayne</u>	<u>(405) 826-7013</u>	<u>wwise@peakviewenergy.com</u>
<u>Walters, Steve</u>	<u>720-402-3081</u>	<u>swalters@peakviewenergy.com</u>

COGCC INSPECTION SUMMARY:

FIR Document Number: 707800247  
Inspection Date: 03/29/2023 FIR Submit Date: 03/31/2023 FIR Status: \_\_\_\_\_

Inspected Operator Information:

Company Name: PEAKVIEW OPERATING COMPANY LLC Company Number: 10409  
Address: 2427 WEST KETTLE CIRCLE  
City: LITTLETON State: CO Zip: 80120

LOCATION - Location ID: 312916

Location Name: VOLOSHIN-MORTON-66N90W Number: 8NESE County: \_\_\_\_\_  
Qtrqr: NESE Sec: 8 Twp: 6N Range: 90W Meridian: 6  
Latitude: 40.491569 Longitude: -107.509158

FACILITY - API Number: 05-081-00 Facility ID: 312916

Facility Name: VOLOSHIN-MORTON-66N90W Number: 8NESE  
Qtrqr: NESE Sec: 8 Twp: 6N Range: 90W Meridian: 6  
Latitude: 40.491569 Longitude: -107.509158

CORRECTIVE ACTIONS:

1  CA# 168824

Corrective Action: Install or repair required BMPs Date: 05/05/2023

Response: CA COMPLETED Date of Completion: 04/26/2023

Operator Comment: Stock piled road base material located at the NW corner of the location, was removed Wednesday April 26, 2023. In the fall of 2022, new containment waddles were placed around the top soil mound.

COGCC Decision: Approved pending re-inspection

COGCC  
Representative:

**OPERATOR COMMENT AND SUBMITTAL**

Comment: One of the attached photos shows that the road base material has been removed, and the other photo shows the straw waddles encompassing the top soil mound.

I hereby certify that the statements made in this form are, to the best of my knowledge, true, correct, and complete.

Print Name: Wayne Wise

Signed: \_\_\_\_\_

Title: Operations Engineer

Date: 5/1/2023 9:18:55 PM

**ATTACHMENT LIST**

View Attachments in Imaged Documents on COGCC website (<http://ogccweblink.state.co.us/>) - Search by Document Number.

<b>Document Number</b>	<b>Description</b>
403390612	FIR RESOLUTION SUBMITTED
403390622	Road Base Removal
403390624	Top Soil Containment

Total Attach: 3 Files