

**FORM
INSP**Rev
X/20**State of Colorado
Oil and Gas Conservation Commission**1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109

Inspection Date:

05/09/2023

Submitted Date:

05/15/2023

Document Number:

707601221

FIELD INSPECTION FORMLoc ID 421609 Inspector Name: Evins, Bret On-Site Inspection ☐ 2A Doc Num: _____**Operator Information:**

OGCC Operator Number: 69175

Name of Operator: PDC ENERGY INC

Address: 1099 18TH STREET SUITE 1500

City: DENVER State: CO Zip: 80202

Status Summary:

- ☐ THIS IS A FOLLOW UP INSPECTION
- ☐ FOLLOW UP INSPECTION REQUIRED
- ☒ NO FOLLOW UP INSPECTION REQUIRED

Findings:

17 Number of Comments

0 Number of Corrective Actions

☐ Corrective Action Response Requested**ANY CORRECTIVE ACTION(S) FROM
PREVIOUS INSPECTIONS THAT HAVE NOT
BEEN ADDRESSED ARE STILL APPLICABLE****Contact Information:**

Contact Name	Phone	Email	Comment
,		cogccinspection@pdce.com	All Inspections

Inspected Facilities:

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
421606	WELL	PR	02/01/2021	OW	123-32972	Wilson 34-34H	PR

General Comment:

This is a WELL / TANK BATTERY inspection.
Well(s): 1: Producing | PR.
Battery: Active.

Centralized Battery serves 1 Tank Battery Facility ID(s)
(Pending).
Centralized Battery serves 1 Location ID(s)
(421609).
(Well(s): 1: Producing | PR).

*Refer to Field Inspection Report doc. #707601223 and/or Location ID #421609 for Well(s) info.
Well(s): 1: Producing | PR.

Location

Lease Road:			
Type	Access		
comment:	Adequate		
Corrective Action		Date:	

Overall Good: ☐

Signs/Marker:			
Type	TANK LABELS/PLACARDS		
Comment:			
Corrective Action:		Date:	
Type	BATTERY		
Comment:			
Corrective Action:		Date:	
Type	CONTAINERS		
Comment:	Coolant, Motor oil, Propane, Paraffin Inhibitor.		
Corrective Action:		Date:	
Type	WELLHEAD		
Comment:			
Corrective Action:		Date:	

Emergency Contact Number:			
Comment:			
Corrective Action:		Date:	

Overall Good: ☐

Spills:					
Type	Area	Volume			
In Containment: No					
Comment:					
<input type="checkbox"/> Multiple Spills and Releases?					

Fencing/:			
Type	SEPARATOR		
Comment:	Surrounded by metal berms & protective shed.		
Corrective Action:		Date:	
Type	WELLHEAD		
Comment:	Iron panel.		
Corrective Action:		Date:	
Type	IGNITOR/COMBUSTOR		
Comment:	Iron panel.		
Corrective Action:		Date:	
Type	PUMP JACK		

Comment: Iron mesh panel.			
Corrective Action:		Date:	
Equipment:			corrective date
Type: Prime Mover	# 1		
Comment: Gas engine drives pump jack. Active.			
Corrective Action:		Date:	
Type: Pump Jack	# 1		
Comment:			
Corrective Action:		Date:	
Type: Bird Protectors	# 3		
Comment:			
Corrective Action:		Date:	
Type: Gas Meter Run	# 1		
Comment: Gas Sales. Calibration card indicates calibration <= 1 year. Last calibration: 04/21/2023. Active w/production.			
Corrective Action:		Date:	
Type: Horizontal Heated Separator	# 1		
Comment:			
Corrective Action:		Date:	
Type: Compressor	# 1		
Comment:			
Corrective Action:		Date:	
Type: Emission Control Device	# 1		
Comment: Crude storage vapor line combustor(s). Controls crude oil tank(s) vapors. Pilots: ON.			
Corrective Action:		Date:	
Type: Ancillary equipment	# 8		
Comment: Battery site: 1: ECD scrubber(s). 1: Solar power bank. 2: Motor oil drum(s) w/ drip containment. Placards. 2: Coolant drum(s) w/ drip containment. Placards. Wellsite: 1: Propane tank. Placards. 1: Paraffin Inhibitor pump(s), tank(s), w/ drip containment. Placards.			
Corrective Action:		Date:	
Type: Vertical Heater Treater	# 1		
Comment:			
Corrective Action:		Date:	

Tanks and Berms:

Contents	#	Capacity	Type	Tank ID	SE GPS	
			CENTRALIZED BATTERY		,	

Comment:	Centralized Battery serves 1 Tank Battery Facility ID(s) (Pending). Centralized Battery serves 1 Location ID(s) (421609). (Well(s): 1: Producing PR).	
Corrective Action:		Date:

Paint

Condition	
Other (Content)	
Other (Capacity)	
Other (Type)	

Berms

Type	Capacity	Permeability (Wall)	Permeability (Base)	Maintenance
Comment:				
Corrective Action:				
				Date:

Contents	#	Capacity	Type	Tank ID	SE GPS
PRODUCED WATER	1	100 BBLS	PBV FIBERGLASS		,
Comment:					
Corrective Action:					
					Date:

Paint

Condition	
Other (Content)	
Other (Capacity)	
Other (Type)	

Berms

Type	Capacity	Permeability (Wall)	Permeability (Base)	Maintenance
Metal	Adequate	Walls Sufficent	Base Sufficent	Adequate
Comment:	Shares berms w/ crude oil tank(s).			
Corrective Action:				
				Date:

Contents	#	Capacity	Type	Tank ID	SE GPS
CRUDE OIL	2	400 BBLS	STEEL AST		40.523223,-104.418337
Comment:					
Corrective Action:					
					Date:

Paint

Condition	Adequate
Other (Content)	
Other (Capacity)	
Other (Type)	

Berms

Type	Capacity	Permeability (Wall)	Permeability (Base)	Maintenance
Metal	Adequate	Walls Sufficent	Base Sufficent	Adequate

Comment:	Shares berms w/ produced H2O tank(s).		
Corrective Action:		Date:	
<u>Venting:</u>			
Yes/No	NO		
Comment:			
Corrective Action:		Date:	
<u>Flaring:</u>			
Type			
Comment:			
Corrective Action:		Date:	

Inspected Facilities									
Facility ID:	421606	Type:	WELL	API Number:	123-32972	Status:	PR	Insp. Status:	PR
Producing Well									
Comment:		Producing PR.							
Corrective Action:								Date:	
BradenHead									
Date of Last Brhd Test:		07/19/2022		Annual Brhd Completed?		Yes			
Last Brhd Test Results		Initial Surf Csg Pressure:		0		Fluid Type:			
		End Surf Csg Pressure:		0					
Comment:									
Corrective Action:								Date:	

Reclamation - Storm Water - Pit**Storm Water:**

Loc Erosion BMPs	BMP Maintenance	Lease Road Erosion BMPs	Lease BMP Maintenance	Chemical BMPs	Chemical BMP Maintenance	Comment
Gravel	Pass	Gravel	Pass	Material Handling And Spill Prevention	Pass	

Comment: Corrective Action: Date: **Pits:** ☐ NO SURFACE INDICATION OF PIT**COGCC Comments**

Comment	User	Date
<p>COGCC Inspection Report Summary:</p> <p>On TUE 05/09/2023 at approximately 15:49 hrs. I, Bret Evins, conducted an on-site inspection at: Operator Name: PDC ENERGY INC Location Name: Wilson/34-34H Location ID: 421609 Tank Battery Facility Name: Pending Tank Battery Facility ID: Pending Well Name(s): Associated w/ Pending Tank Battery Name & ID. Wilson 34-34H. API: Associated w/ Pending Tank Battery Name & ID. 123-32972. Location County: Weld County, Colorado Weather: Mostly Sunny, dry.</p> <p>While there, I observed: Well(s): 1: Producing PR. Battery: Active.</p> <p>Centralized Battery serves 1 Tank Battery Facility ID(s) (Pending). Centralized Battery serves 1 Location ID(s) (421609). (Well(s): 1: Producing PR).</p> <p>*Refer to Field Inspection Report doc. #707601223 and/or Location ID #421609 for Well(s) info. Well(s): 1: Producing PR.</p> <p>During this inspection, NO possible compliance issues were observed.</p> <p>This is a summary of the inspection report.</p>	evinsb	05/15/2023

Attached DocumentsYou can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
707601222	Site photo(s)	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=6114839