

**FORM
INSP**Rev
X/20**State of Colorado
Oil and Gas Conservation Commission**1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109

Inspection Date:

05/09/2023

Submitted Date:

05/15/2023

Document Number:

707601225

FIELD INSPECTION FORMLoc ID 425363 Inspector Name: Evins, Bret On-Site Inspection ☐ 2A Doc Num: _____**Operator Information:**

OGCC Operator Number: 69175

Name of Operator: PDC ENERGY INC

Address: 1099 18TH STREET SUITE 1500

City: DENVER State: CO Zip: 80202

Status Summary:

- ☐ THIS IS A FOLLOW UP INSPECTION
- ☐ FOLLOW UP INSPECTION REQUIRED
- ☒ NO FOLLOW UP INSPECTION REQUIRED

Findings:

18 Number of Comments

0 Number of Corrective Actions

☐ Corrective Action Response Requested**ANY CORRECTIVE ACTION(S) FROM
PREVIOUS INSPECTIONS THAT HAVE NOT
BEEN ADDRESSED ARE STILL APPLICABLE****Contact Information:**

Contact Name	Phone	Email	Comment
,		cogccinspection@pdce.com	All Inspections

Inspected Facilities:

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
425368	WELL	PR	10/01/2017	OW	123-34358	Wilson 14-34H	PR

General Comment:

This is a WELL / TANK BATTERY inspection.

Well(s): 1: Producing | PR.

Battery: Active.

Centralized Battery serves 1 Tank Battery Facility ID(s)

(Pending).

Centralized Battery serves 1 Location ID(s)

(425363).

(Well(s): 1: Producing | PR).

*Refer to Field Inspection Report doc. #707601227 and/or Location ID #425363 for Well(s) info.

Well(s): 1: Producing | PR.

Location

Lease Road:			
Type	Access		
comment:	Adequate		
Corrective Action:		Date:	

Overall Good: ☐

Signs/Marker:			
Type	CONTAINERS		
Comment:	Methanol.		
Corrective Action:		Date:	
Type	WELLHEAD		
Comment:			
Corrective Action:		Date:	
Type	BATTERY		
Comment:			
Corrective Action:		Date:	
Type	TANK LABELS/PLACARDS		
Comment:			
Corrective Action:		Date:	

Emergency Contact Number:

Comment:

Corrective Action: Date:

Overall Good: ☐

Spills:				
Type	Area	Volume		

In Containment: No

Comment: ☐ Multiple Spills and Releases?

Fencing/:			
Type	SEPARATOR		
Comment:	Surrounded by metal berms & protective shed.		
Corrective Action:		Date:	
Type	IGNITOR/COMBUSTOR		
Comment:	Iron panel.		
Corrective Action:		Date:	
Type	WELLHEAD		
Comment:	Iron panel.		
Corrective Action:		Date:	

Equipment:			corrective date
Type: Plunger Lift	# 1		
Comment:			
Corrective Action:			Date:
Type: Gas Meter Run	# 1		
Comment:	Gas Sales. Calibration card indicates calibration <= 1 year. Last calibration: 04/21/2023. Active w/production.		
Corrective Action:			Date:
Type: Compressor	# 1		
Comment:	At wellsite.		
Corrective Action:			Date:
Type: Vertical Heater Treater	# 1		
Comment:			
Corrective Action:			Date:
Type: Bird Protectors	# 3		
Comment:			
Corrective Action:			Date:
Type: Bradenhead	# 1		
Comment:	Appears plumbed to surface.		
Corrective Action:			Date:
Type: Horizontal Heated Separator	# 1		
Comment:			
Corrective Action:			Date:
Type: Emission Control Device	# 1		
Comment:	Crude storage vapor line combustor(s). Controls crude oil tank(s) vapors. Pilots: ON.		
Corrective Action:			Date:
Type: Ancillary equipment	# 2		
Comment:	Battery site. 1: Methanol pump(s), tank(s) w/ drip containment. Placards. 1: ECD scrubber(s).		
Corrective Action:			Date:

Tanks and Berms:

Contents	#	Capacity	Type	Tank ID	SE GPS
			CENTRALIZED BATTERY		,
Comment:	Centralized Battery serves 1 Tank Battery Facility ID(s) (Pending). Centralized Battery serves 1 Location ID(s) (425363). (Well(s): 1: Producing PR).				
Corrective Action:					Date:

Paint

Condition	
Other (Content)	

Other (Capacity)						
Other (Type)						
<u>Berms</u>						
Type	Capacity	Permeability (Wall)	Permeability (Base)	Maintenance		
Comment:						
Corrective Action:				Date:		
Contents	#	Capacity	Type	Tank ID	SE GPS	
PRODUCED WATER	1	100 BBLs	PBV FIBERGLASS		,	
Comment:						
Corrective Action:				Date:		
<u>Paint</u>						
Condition						
Other (Content)						
Other (Capacity)						
Other (Type)						
<u>Berms</u>						
Type	Capacity	Permeability (Wall)	Permeability (Base)	Maintenance		
Metal	Adequate	Walls Sufficient	Base Sufficient	Adequate		
Comment: Shares berms w/ crude oil tank(s).						
Corrective Action:				Date:		
Contents	#	Capacity	Type	Tank ID	SE GPS	
CRUDE OIL	2	400 BBLs	STEEL AST		40.523244,-104.430649	
Comment: Equalizer line(s) connect crude oil tank(s).						
Corrective Action:				Date:		
<u>Paint</u>						
Condition	Adequate					
Other (Content)						
Other (Capacity)						
Other (Type)						
<u>Berms</u>						
Type	Capacity	Permeability (Wall)	Permeability (Base)	Maintenance		
Metal	Adequate	Walls Sufficient	Base Sufficient	Adequate		
Comment: Shares berms w/ produced H2O tank(s).						
Corrective Action:				Date:		
<u>Venting:</u>						
Yes/No	NO					
Comment:						
Corrective Action:				Date:		
<u>Flaring:</u>						

Type		
Comment:		
Corrective Action:		Date:

Inspected Facilities									
Facility ID:	425368	Type:	WELL	API Number:	123-34358	Status:	PR	Insp. Status:	PR
Producing Well									
Comment:		Producing PR.							
Corrective Action:								Date:	
BradenHead									
Date of Last Brhd Test:		07/19/2022		Annual Brhd Completed?		Yes			
Last Brhd Test Results		Initial Surf Csg Pressure:		0		Fluid Type:			
		End Surf Csg Pressure:		0					
Comment:									
Corrective Action:								Date:	

Reclamation - Storm Water - Pit**Storm Water:**

Loc Erosion BMPs	BMP Maintenance	Lease Road Erosion BMPs	Lease BMP Maintenance	Chemical BMPs	Chemical BMP Maintenance	Comment
Gravel	Pass	Gravel	Pass	Material Handling And Spill Prevention	Pass	

Comment: Corrective Action: Date: **Pits:** ☐ NO SURFACE INDICATION OF PIT**COGCC Comments**

Comment	User	Date
<p>COGCC Inspection Report Summary:</p> <p>On TUE 05/09/2023 at approximately 13:38 hrs. I, Bret Evins, conducted an on-site inspection at: Operator Name: PDC ENERGY INC Location Name: Wilson/14-34H Pad Location ID: 425363 Tank Battery Facility Name: Pending Tank Battery Facility ID: Pending Well Name(s): Associated w/ Pending Tank Battery Name & ID. Wilson 14-34H. API: Associated w/ Pending Tank Battery Name & ID. 123-34358. Location County: Weld County, Colorado Weather: Mostly Sunny, dry.</p> <p>While there, I observed: Well(s): 1: Producing PR. Battery: Active. Centralized Battery serves 1 Tank Battery Facility ID(s) (Pending). Centralized Battery serves 1 Location ID(s) (425363). (Well(s): 1: Producing PR).</p> <p>*Refer to Field Inspection Report doc. #707601227 and/or Location ID #425363 for Well(s) info. Well(s): 1: Producing PR.</p> <p>During this inspection, NO possible compliance issues were observed.</p> <p>This is a summary of the inspection report.</p>	evinsb	05/15/2023

Attached DocumentsYou can go to COGCC Images (<https://cogcc.state.co.us/webblink/>) and search by document number:

Document Num	Description	URL
707601226	Site photo(s)	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=6114841