

Inspection Photos
Location Name: State 16-3-61
Location ID: 427445



Photo 1 – ECD



Photo 2 – Tank Battery

Inspection Photos
Location Name: State 16-3-61
Location ID: 427445




Photo 3 – Stained Soil at Tanks



Photo 4 – Tank Battery Sign

Inspection Photos
Location Name: State 16-3-61
Location ID: 427445



Photo 5 – Heater Treater



Photo 6 – Propane Tank

Inspection Photos
Location Name: State 16-3-61
Location ID: 427445



Photo 7 – Flare



Photo 8 – Stained Soil at NW Corner of Location

Inspection Photos
Location Name: State 16-3-61
Location ID: 427445



Photo 9 – Unused Parts



Photo 10 – Stained Soil at Wellhead

Inspection Photos
Location Name: State 16-3-61
Location ID: 427445



Photo 11 – Pumping Unit



Photo 12 – Stained Soil at Wellhead

Inspection Photos
Location Name: State 16-3-61
Location ID: 427445




Photo 13 – Wellhead – Stained Soil and Unmarked Riser