

# CAERUS PICEANCE LLC, KEINATH FEDERAL-68S96W/18SWNE

## Location #334316



**NW Corner of Location – Photo #03346**



**NE Corner of Location – Photo #03347**

# CAERUS PICEANCE LLC, KEINATH FEDERAL-68S96W/18SWNE

## Location #334316



**SE Corner of Location – Photo #03348**



**SW Corner of Location – Photo #03349**

# CAERUS PICEANCE LLC, KEINATH FEDERAL-68S96W/18SWNE

Location #334316



Wellhead – Photo #03351



Gas Meter/Separator – Photo #03353

# CAERUS PICEANCE LLC, KEINATH FEDERAL-68S96W/18SWNE

## Location #334316



**Tank Battery – Photo #03357**



**Location Lacks Stabilization – Photo #03350**

# CAERUS PICEANCE LLC, KEINATH FEDERAL-68S96W/18SWNE

## Location #334316



**Wildlife Entry Hazard – Photo #03359**



**Berm Eroding onto Location – Photo #03356**

# CAERUS PICEANCE LLC, KEINATH FEDERAL-68S96W/18SWNE

## Location #334316



**Berm Eroding onto Location – Photo #03361**



**Insufficient Vehicle Tracking BMPs at Location Entrance/Exit – Photo #03362**