

Inspection Photos

Location Name: CAERUS PICEANCE LLC COUEY C17AE Pad

Location #: 334792



Photo # 7707 From entrance to location



Photo # 7708 Location

Inspection Photos

Location Name: CAERUS PICEANCE LLC COUEY C17AE Pad

Location #: 334792



May 15, 2023 at 10:06:31 AM
CO



May 15, 2023 at 10:06:42 AM
CO

Photo # 7709 Location

Photo # 7710 Location

Inspection Photos

Location Name: CAERUS PICEANCE LLC COUEY C17AE Pad

Location #: 334792



Photo # 7734 Chemical containment full/failure to maintain chemical BMP



Photo # 7740 Chemical containment 7/8th full/failure to maintain chemical BMP

Inspection Photos
Location Name: CAERUS PICEANCE LLC COUEY C17AE Pad
Location #: 334792



Photo # 7748 Barbed wire/wildlife hazard



Photo # 7749 Barbed wire/wildlife hazard