

Inspection Photos

Location Name: CAERUS PICEANCE LLC COUEY C17E Pad

Location #: 334797



Photo # 7762 From entrance to location



Photo # 7763 From entrance to location

Inspection Photos

Location Name: CAERUS PICEANCE LLC COUEY C17E Pad

Location #: 334797



Photo # 7764 From entrance to location



Photo # 7765 Location

Inspection Photos
Location Name: CAERUS PICEANCE LLC COUEY C17E Pad
Location #: 334797



May 15, 2023 at 10:31:40 AM
CO



May 15, 2023 at 10:31:58 AM
CO

Photo # 7766 Location

Photo # 7767 Location

Inspection Photos

Location Name: CAERUS PICEANCE LLC COUEY C17E Pad

Location #: 334797



Photo # 7768 Location



Photo # 7778 Containment liner needs maintenance

Inspection Photos

Location Name: CAERUS PICEANCE LLC COUEY C17E Pad

Location #: 334797



Photo # 7779 Containment liner needs maintenance



Photo # 7780 Containment liner needs maintenance

Inspection Photos

Location Name: CAERUS PICEANCE LLC COUEY C17E Pad

Location #: 334797



Photo # 7783 Containment liner needs maintenance



Photo # 7784 Containment liner needs maintenance

Inspection Photos

Location Name: CAERUS PICEANCE LLC COUEY C17E Pad

Location #: 334797



Photo # 7781 Containment liner needs maintenance



Photo # 7787 Improperly marked deadman

Inspection Photos
Location Name: CAERUS PICEANCE LLC COUEY C17E Pad
Location #: 334797



Photo # 7780 Debris



Photo # 7789 Debris