

Storm water Management and Erosion control
Location Name: CAERUS PICEANCE LLC J32 Pad
Location #: 334822



North West corner of location.



North East corner of location.



South West corner of location.



South East corner of location.

Storm water Management and Erosion control
Location Name: CAERUS PICEANCE LLC J32 Pad
Location #: 334822



Photo # 7565 Berm & ditch need maintenance



Photo # 7568 Culvert needs maintenance (unable to locate other end of culvert, possibly crimped & buried under sediment)

Storm water Management and Erosion control
Location Name: CAERUS PICEANCE LLC J32 Pad
Location #: 334822



Photo # 7569 Culvert needs maintenance (unable to locate other end of culvert, possibly crimped & buried under sediment)



Photo # 7570 Sediment trap needs maintenance

Storm water Management and Erosion control
Location Name: CAERUS PICEANCE LLC J32 Pad
Location #: 334822



Photo # 7576 Ditch & berm needs maintenance