

Inspection Photos
Location Name: CAERUS PICEANCE LLC N8E Pad
Location #: 334782



Photo # 7825 From entrance to location



Photo # 7826 From entrance to location

Inspection Photos
Location Name: CAERUS PICEANCE LLC N8E Pad
Location #: 334782



Photo # 7828 Location

Photo # 7830 Location

Inspection Photos
Location Name: CAERUS PICEANCE LLC N8E Pad
Location #: 334782



Photo # 7831 Location




Photo # 7832 Debris

Inspection Photos
Location Name: CAERUS PICEANCE LLC N8E Pad
Location #: 334782



Photo # 7847 Barbed wire/wildlife hazard