

## Inspection Photos

Location Name: TEP ROCKY MOUNTAIN LLC BATTLEMENT MESA-67S95W /9NENE

Location ID: 334964



Photo #9936 From entrance to location.



Photo #9937 From entrance to location

## Inspection Photos

Location Name: TEP ROCKY MOUNTAIN LLC BATTLEMENT MESA-67S95W /9NENE

Location ID: 334964



Photo #9938 From entrance to location.



Photo #9939 Secondary containment capacity reduced

## Inspection Photos

Location Name: TEP ROCKY MOUNTAIN LLC BATTLEMENT MESA-67S95W /9NENE

Location ID: 334964



Photo #9941 Secondary containment capacity reduced.



Photo #9943 Calibration cards not conspicuously posted.

## Inspection Photos

Location Name: TEP ROCKY MOUNTAIN LLC BATTLEMENT MESA-67S95W /9NENE

Location ID: 334964



Photo #9940 Loadline open ended.