

**FORM
INSP**

Rev
X/20

**State of Colorado
Oil and Gas Conservation Commission**

1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109



Inspection Date:

05/15/2023

Submitted Date:

05/16/2023

Document Number:

707601229

FIELD INSPECTION FORM

Loc ID: 305365 Inspector Name: Evins, Bret On-Site Inspection: 2A Doc Num: _____

Status Summary:

- THIS IS A FOLLOW UP INSPECTION
- FOLLOW UP INSPECTION REQUIRED
- NO FOLLOW UP INSPECTION REQUIRED

Findings:

11 Number of Comments
0 Number of Corrective Actions
 Corrective Action Response Requested

ANY CORRECTIVE ACTION(S) FROM PREVIOUS INSPECTIONS THAT HAVE NOT BEEN ADDRESSED ARE STILL APPLICABLE

Operator Information:

OGCC Operator Number: 100322
Name of Operator: NOBLE ENERGY INC
Address: 2001 16TH STREET SUITE 900
City: DENVER State: CO Zip: 80202

Contact Information:

| Contact Name | Phone | Email | Comment |
|--------------|-------|---------------------------------------------------|---------------------------------|
| | | dnr_cogccengineering@state.co.us | |
| | | rbucogccinspectionreports@chevron.onmicrosoft.com | All Inspections |

Inspected Facilities:

| Facility ID | Type | Status | Status Date | Well Class | API Num | Facility Name | Insp Status |
|-------------|------|--------|-------------|------------|-----------|---------------|-------------|
| 276892 | WELL | PR | 10/01/2020 | GW | 123-22859 | SHARKEY 32-35 | PA |

General Comment:

This is a **PLUGGED & ABANDONED WELL** inspection.
Well(s): 1: Plugged & Abandoned | PA.
Battery: Abandoned. ALL equipment has been removed.

Abandoned Centralized Battery formerly served 3 Location IDs (305251, 305365, 305891).
(Well(s): 1: Temporarily Abandoned | TA ;2: Plugged & Abandoned | PA).
Abandoned Battery GPS coord: 40.447421 / -104.516984

Location

Overall Good:

Emergency Contact Number:

Comment:

Corrective Action:

Date: _____

Overall Good:

Spills:

| Type | Area | Volume | | | |
|------|------|--------|--|--|--|
| | | | | | |

In Containment: No

Comment:

Multiple Spills and Releases?

Equipment:

| Type | Area | Volume | | | corrective date |
|-----------------------------|-----------------------------------------------------------------|--------|--|--|-----------------|
| Horizontal Heated Separator | # 0 | | | | |
| Comment: | Plugged & Abandoned PA. Battery Abandoned. Equipment removed. | | | | |
| Corrective Action: | | | | | Date: |
| Emission Control Device | # 0 | | | | |
| Comment: | Plugged & Abandoned PA. Battery Abandoned. Equipment removed. | | | | |
| Corrective Action: | | | | | Date: |
| Pig Station | # 0 | | | | |
| Comment: | Plugged & Abandoned PA. Battery Abandoned. Equipment removed. | | | | |
| Corrective Action: | | | | | Date: |
| Ancillary equipment | # 0 | | | | |
| Comment: | Plugged & Abandoned PA. Battery Abandoned. Equipment removed. | | | | |
| Corrective Action: | | | | | Date: |
| Gas Meter Run | # 0 | | | | |
| Comment: | Plugged & Abandoned PA. Battery Abandoned. Equipment removed. | | | | |
| Corrective Action: | | | | | Date: |
| Plunger Lift | # 0 | | | | |
| Comment: | Plugged & Abandoned PA. Equipment removed. | | | | |
| Corrective Action: | | | | | Date: |

Tanks and Berms:

| Contents | # | Capacity | Type | Tank ID | SE GPS |
|--------------------|-----------------------------------------------------------------|----------|------|---------|--------|
| PRODUCED WATER | 0 | | | | |
| Comment: | Plugged & Abandoned PA. Battery Abandoned. Equipment removed. | | | | |
| Corrective Action: | | | | | Date: |

Paint

| Condition | |
|-----------|--|
| | |

| | |
|------------------|--|
| Other (Content) | |
| Other (Capacity) | |
| Other (Type) | |

Berms

| Type | Capacity | Permeability (Wall) | Permeability (Base) | Maintenance |
|--------------------|----------|---------------------|---------------------|-------------|
| | | | | |
| Comment: | | | | |
| Corrective Action: | | | | Date: |

| Contents | # | Capacity | Type | Tank ID | SE GPS |
|--------------------|-----------------------------------------------------------------|----------|------|---------|--------|
| CRUDE OIL | 0 | | | | |
| Comment: | Plugged & Abandoned PA. Battery Abandoned. Equipment removed. | | | | |
| Corrective Action: | | | | Date: | |

Paint

| | |
|------------------|--|
| Condition | |
| Other (Content) | |
| Other (Capacity) | |
| Other (Type) | |

Berms

| Type | Capacity | Permeability (Wall) | Permeability (Base) | Maintenance |
|--------------------|----------|---------------------|---------------------|-------------|
| | | | | |
| Comment: | | | | |
| Corrective Action: | | | | Date: |

Venting:

| | | |
|--------------------|--|-------|
| Yes/No | | |
| Comment: | | |
| Corrective Action: | | Date: |

Flaring:

| | |
|--------------------|-------|
| Type | |
| Comment: | |
| Corrective Action: | Date: |

Inspected FacilitiesFacility ID: 276892 Type: WELL API Number: 123-22859 Status: PR Insp. Status: PA**COGCC Comments**

| Comment | User | Date |
|-------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------|--------|------------|
| <p>COGCC Inspection Report Summary:</p> <p>On MON 05/15/2023 at approximately 15:32 hrs. I, Bret Evins, conducted an on-site inspection at: Operator Name: NOBLE ENERGY INC Location Name: SHARKEY-66N64W/35SWNE Location ID: 305365 Well Name(s): Sharkey 32-35. API: 123-22859. Location County: Weld County, Colorado Weather: Partly Sunny, damp from prior storm.</p> <p>While there, I observed: Well(s): 1: Plugged & Abandoned PA. Battery: Abandoned. ALL equipment has been removed.</p> <p>Abandoned Centralized Battery formerly served 3 Location IDs (305251, 305365, 305891). (Well(s): 1: Temporarily Abandoned TA ;2: Plugged & Abandoned PA). Abandoned Battery GPS coord: 40.447421 / -104.516984</p> <p>WELL STATUS COMMENT: Plugged & Abandoned PA. Form 6S on file. Plugging, cut/cap date: 02/03/2022. Approval Pending. Plugged & Abandoned PA well GPS coordinates: 40.444110 / -104.514690</p> <p>During this inspection, NO possible compliance issues were observed.</p> <p>This is a summary of the inspection report.</p> | evinsb | 05/16/2023 |

Attached DocumentsYou can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

| Document Num | Description | URL |
|--------------|---------------|---------------------------------------------------------------------------------------------------------------------------------------------------------------------|
| 707601230 | Site photo(s) | http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=6115751 |