

Interim Reclamation and Stormwater Inspection

May 11, 2023

Operator: UPLAND EXPLORATION LLC- #10701

Location ID: 462908

Inspection Document #: 697504668

Weld County, CO

NESE Section 21 T11N R64W

Chris Binschus
Reclamation Specialist, COGCC



COLORADO
**Oil & Gas Conservation
Commission**

Department of Natural Resources

Inspection Photos
Location Name: Little Lady 21/North Well Pad
Location ID: 462908



Photo 1. Photo taken from the southeastern location, facing North. Photo illustrates interim reclamation has been performed; however, interim reclamation is not complete due to the lack of soil stabilization. It appears that straw mulch was crimped but blew away in a dust storm.



Photo 2. Photo taken from the southeastern location, facing Northeast. Photo illustrates the what appears to be the straw mulch that blew away in a dust storm.

Inspection Photos

Location Name: Little Lady 21/North Well Pad

Location ID: 462908



Photo 3. Photo taken from the southern location, facing North. See comments under Photo 1.



Photo 4. Photo taken from the southwestern location, facing North. See comments under Photo 1.



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

Inspection Number: 697504668

Inspection Photos
Location Name: Little Lady 21/North Well Pad
Location ID: 462908



Photo 5. Photo taken from the western location, facing West. Photo illustrates stained soil around the compressors has been removed.



Photo 6. Photo taken from the western location, facing West. See comments under Photo 5.

Inspection Photos
Location Name: Little Lady 21/North Well Pad
Location ID: 462908



Photo 7. Photo taken from the topsoil stockpile, facing East. Photo illustrates the topsoil stockpile which has been seeded; however, the topsoil stockpile lacks soil stabilization.



Photo 8. Photo taken from the facility location. Photo illustrates an open bucket with oil that is missing wildlife protection devices.



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

Inspection Number: 697504668