

## Inspection Photos

Location Name: CAERUS PICEANCE LLC BENTLEY-67S95W /11SWNE

Location ID: 334625



Photo #9944 From entrance to location.



Photo #9945 From entrance to location

## Inspection Photos

Location Name: CAERUS PICEANCE LLC BENTLEY-67S95W /11SWNE

Location ID: 334625



**Photo #9946 Flowline heating insulation open ended and not capped.**